


Ladder Editor Compatibility with Windows 11

Introduction

After installing Ladder Editor on a computer running Windows 11, it may no longer function. The error “Hardware Key is missing” might appear.



Solution

This is most likely caused by an older version of Ladder Editor. Ladder Editor for YRC1000 version 3.30 can be found [here](#) or ask Partner Support for the install.

Ladder Editor for DX200 needs to be requested from Partner Support.

Notes

Ladder Editor for DX100 and FS100 will not support Windows 11. A virtual machine is recommended for the continued support of these older controllers.